



MU524 Setup guide

Follow the testing procedure in the shown order. If one test fails, find out the problem, correct it then resume.

Always unplug power between steps because it is very easy to create a short circuit when moving a DMM probe. And most of the time, shortcuts are fatal to the circuits.

Step	Description
1. Board installation (without XT500)	Remove all other modules from your 500 rack or Lunchbox and insert the MU524 into the leftmost slot.
2. Board installation (with XT500)	Connect the MU524 to your XT500.
3. Initial configuration	<ul style="list-style-type: none"> <input type="checkbox"/> Bypass on centre position (bypassed). <input type="checkbox"/> All push switches released (up). <input type="checkbox"/> IN potentiometer on 10. <input type="checkbox"/> OUT potentiometer on 0. <input type="checkbox"/> REC. (release) pot on 10. <input type="checkbox"/> Jumper JMP1 removed.
4. Tube heater slow start test	<ul style="list-style-type: none"> <input type="checkbox"/> Set your DMM to DC Volts. <input type="checkbox"/> Place the meter probes between the 2 side pins of the tube holder PCB, <div data-bbox="703 1010 1305 1240" style="text-align: center;"> </div> <ul style="list-style-type: none"> <input type="checkbox"/> Power up the lunchbox and check that the voltage slowly increases from 1 to 2V as the tube gets hot then more rapidly to 6V after 10 seconds. <input type="checkbox"/> Power off.
5. Power voltages check	<ul style="list-style-type: none"> <input type="checkbox"/> Connect the black probe to test point 0V. <input type="checkbox"/> Power up. <input type="checkbox"/> Connect the red probe to test point V+. Check that you get a value between +15 and +16 Volts. <input type="checkbox"/> Connect the red probe to test point V-. Check that you get a value between -15 and -16 Volts. <input type="checkbox"/> Connect the red probe to test point B+. Check that you get a value between +45 and +48 Volts. <input type="checkbox"/> Set the Bypass switch to IN and check that the dB meter lights up.
6. Audio path check	<ul style="list-style-type: none"> <input type="checkbox"/> Connect a 1.0VAC, 1KHz sine source to the input. You can use your multitrack software (DAW) to play a sine tone like the one that is downloadable from the "Support/Downloads & Useful links" section on our website. <input type="checkbox"/> Connect your DMM to the MU524, between pin 2 and pin 3 of the output XLR (XT500 pins 2&4). The DMM is set to AC Voltage. <input type="checkbox"/> Set Bypass to the centre position (bypassed). <input type="checkbox"/> Adjust the signal amplitude from the DAW in order to read 1.0 VAC on the DMM. <input type="checkbox"/> Set Bypass to the left position (compressor on).



Step		Description
		<ul style="list-style-type: none"> <input type="checkbox"/> Check that the output voltage has risen to 3-4 VAC. <input type="checkbox"/> Turn the OUT potentiometer and check that it increases the output voltage up to 9VAC or more.
7.	Tube balance 1 (balance at no attenuation)	<p>The tube must have been heating for 15mn minimum before doing the following adjustments. It is best not to turn off the power between these settings.</p> <ul style="list-style-type: none"> <input type="checkbox"/> Set your DMM to DC volts and connect it between test pins TP1 and TP2. <input type="checkbox"/> Adjust TR2 (Bal1) in order to read 0 volts. Use the smallest voltage range on the meter for the best precision.
8.	Tube balance 2 (balance at -6dB attenuation)	<ul style="list-style-type: none"> <input type="checkbox"/> Set TR4 (Vref) all the way up, 20 turns CW (clockwise). <input type="checkbox"/> Set TR5 (Atn2) all the way down, 20 turns CCW (counter clockwise). <input type="checkbox"/> Set TR3 (Atn1) all the way down, 20 turns CCW (counter clockwise). <input type="checkbox"/> Place the jumper on JMP1 across pins 2-3 (pin 1 is identified by a white dot). <input type="checkbox"/> Set the DMM to AC volts and connect it the output, between pin 2 and pin 3 of the output XLR (XT500 pins 2#4). Adjust the OUT potentiometer in order to read 6.0VAC (do not touch the other potentiometers). <input type="checkbox"/> Adjust TR4 (Vref) until you read 3.0VAC. <input type="checkbox"/> Set the DMM to DC volts and connect it between test pins TP1 and TP2. <input type="checkbox"/> Adjust TR1 (Bal2) in order to read 0 volts.
9.	Side chain setup -3dB @ -2V	<ul style="list-style-type: none"> <input type="checkbox"/> Set the DMM to DC volts and connect it between test pins TP6 and OV. <input type="checkbox"/> Adjust TR4 (Vref) in order ton read -2VDC on the DMM. <input type="checkbox"/> Set the DMM to AC volts and connect it to the output, between pin 2 and pin 3 of the output XLR (XT500 pins 2#4). <input type="checkbox"/> Remove the jumper and adjust the OUT potentiometer in order to read 6.0VAC on the DMM (do not touch the other potentiometers). <input type="checkbox"/> Place the jumper on JMP1 across pins 2-3 and adjust TR3 (Atn1) in order to read 4.25VAC on the DMM (3dB attenuation).
10.	Side chain setup -6dB @ -3.6V	<ul style="list-style-type: none"> <input type="checkbox"/> Set the DMM to DC volts and connect it between test pins TP6 and OV. <input type="checkbox"/> Adjust TR4 (Vref) in order ton read -3.6VDC on the DMM. <input type="checkbox"/> Set the DMM to AC volts and connect it to the output, between pin 2 and pin 3 of the output XLR (XT500 pins 2#4). <input type="checkbox"/> Adjust TR5 (Atn2) in order to read 3.00VAC on the DMM (6dB attenuation).
11.	Meter setup	<ul style="list-style-type: none"> <input type="checkbox"/> Adjust TR6 (Meter) in order to read -6dB attenuation on the front panel meter.
12.	General check	<ul style="list-style-type: none"> <input type="checkbox"/> Place the jumper on JMP1 across pins 1-2. <p>Send a musical program to the input and verify that all the front panel controls work as expected.</p>
13.	Congratulations!	You're done!