

TS500 phase restore modification

the picture shows the back of the PCB, upper right corner.

- make 4 track cuts (white lines in the picture). Check before and after cut with your DMM in bell ring mode.
- Add wire links 1 and 2 (red in the picture).
- Add 1 resistor 10k (red in the picture).
- Add insulated wire 3 (yellow in the picture)

