



C14, C15 not connected in case of SK47 DOA, 47pF in all other cases



T1, RZ1, CZ1 : see mp32-output-tx-options.pdf



|                       |                               |                       |               |          |
|-----------------------|-------------------------------|-----------------------|---------------|----------|
| <b>SOUND SKULPTOR</b> | Title                         | MP32 Component Layout | Sch Rev       | 1.2      |
|                       | www.soundskulptor.com         |                       | PCB Rev       | 1.2      |
|                       | Copyright ©2007 Soundskulptor |                       | Last modified | 03/10/07 |